

#### Health and Safety Tree Survey for Admirals Way Allotment site, Andover (November 2023)

Client						Arboric	ultural Co	onsultant			Amelia Williams MICFor, CEnv, MArbora, BSc (Hons), Cert EdF.E, Dip Arb L6 (ABC), Cert Arb L4 (ABC)				at time of Cold, dry, light breez		-					
Site locatio	n		Adm	irals \	Way Allotments,	Andover				Site obs	ervation	s				ne padlocked gate. Overhead services along the vned land managed by Aster Property Services.						
Date of the	Date of the tree survey			22.11.2023 Des											No Tree Preservation Order (TPO) confirmed by TVBC on 06.11.2023 and site not within a Conservation Area (CA)			Plotted	Yes on Ezytre tagged		Next inspection date	2028
Full Code	Seq No	Species (Botanical name / Common name)	Ash	Privat	e Tree Position	Addn. Position	No. of Stems	No. of Trees	Height (m)	Spread (m (d))	Trunk diameter	Age range	Vigour	Condition	Site features	Tree considerations	Tree management recommendations	Priority for tree work	r Failure (THREATS)	Target (THREATS)	Impact (THREATS)	Risk Cat (THREATS)
Grp/001241	G1	Hedge - Mixed Native Cornus sanguinea - (1) Hedera helix - (1) Rosa canina - (1)	No	Yes	Private offsite Western boundary	by main gate outside fence	3	3	4	2	5	Young	Normal	Fair	Fence within falling distance     Fence under canopy     Cate or entrance     Grass surround     Underground services	Crown shape distorted due to group pressure - The majority of stems grow on land outside the boundary fence on land owned by Test Valley Borough Council but managed by Aster Property Services. I yo or climbing plants I yo covered tree Multi stemmed	- Hedge pruning maintenance - Prune back to the fence line annually as part of boundary maintenance within the fence side of the allotments to maintain the gateway access. (x 3 tree)	Routine	None apparent	Low	Fragile objects	Insignificant
Grp/001242	G2	Hedge - Mixed Native Cornus sanguinea - (3) Rosa canina - (3)	No	Yes	Private offsite Western boundary	Outside fence	6	6	4	4	9	Middle aged	Normal	Fair	- Fence within falling distance - Fence under canopy - Grass surround	Crown shape distorted due to group pressure - The majority of stems grow on land outside the boundary fence on land owned by Test Valley Borough Council but managed by Aster Property Services.     Multi stemmed	Hedge pruning maintenance - Annually prune back to boundary as part of boundary maintenance within the allotment site. (x 6 tree)	Routine	None apparent	Low	Fragile objects	Insignificant
SgI/001243	1	Sambucus nigra (Common Elder)	No	No	Western boundary	Growing up against the boundary fence	3	1	3	3	15	Over mature	Low	Very poor	Fence within falling distance     Fence under canopy     Grass surround	Dead / dying     Decay present     Fungal fruiting bodies     Trifurcated     Wildlife habitat - bird feeder on branch	Retain, no works currently recommended - for wildlife purposes	Routine	Potentially	Low	Fragile objects	Insignificant
Grp/001244	G3	Mixed broadleaves. Cornus sanguinea - (30) Fraxinus excelsior - (1) Prunus spinosa - (1)	No	No	On and off site group	Western to Northern boundary	32	32	4	4	10	Middle aged	Normal	Fair	- Fence within falling distance - Fence under canopy - Grass surround - Wildlife Habitat - plus storage of trailer and other wood	-Crown shape distorted due to group pressure - The majority of stems grow on land outside the boundary fence on land owned by Test Valley Borough Council lot un ananged by Aster Property Services. Land to the Eastern boundary under Harmpshire County Council ownership. Low hanging branches - branches growing through fence - Multi stemmed	- Hedge pruning maintenance - Prune back as part of annual fence boundary maintenance. (x 1 tree)	Routine	None apparent	Low	Fragile objects	Insignificant
Grp/001245	G4	Crataegus monogyna (Hawthorn)	No	Yes	Private off site group	Eastern boundary HCC	6	6	7	6	25	Middle aged	Normal	Fair	- Fence within falling distance - Fence under canopy	Crown shape distorted due to group pressure Group assessment - Private group off site behin boundary fence overhanging into the site. Owned by Hampshire County Council. I vy or climbing plants I vy covered tree Unable to fully assess due to restricted access Unable to fully assess due to ivy	Sever climbing plant - Recommend contacting HCC to sever ivy and request health and safety inspection of the off-site trees overhanging the site. (x. 6 tree)	Routine	Potentially	Low	Minor damage	Insignificant
Sgl/001246	2	Fraxinus excelsior (Common Ash)	Yes	Yes	Private offsite tree	owned by HCC	3	1	9	5	25	Young	Normal	Fair	- Fence within falling distance - Fence under canopy - Shed - plus greenhouse	Ash dieback - Ash stage 1 = 76-100% canopy remaining - Branch stubs present - Crown lifted - over the site boundary historically - Crown shape distorted due to group pressure - Epicormic growth - lyo or climbing plants - lyo covered tree - Triffurcated - Unable to fully assess due to restricted access - Land owner Hampshire County Council Unable to fully assess due to ivy	Monitor (Annually) - HCC to monitor, the Ash dieback     Sever climbing plant - Request HCC to sever ivy to aid with future inspections.		Potentially	Medium	Minor damage	Minimal
Sgl/001247	3	Ulmus glabra (Wych Elm)	No	No	Behind the shed	Eastern boundary	1	1	10	4	24	Young	Low	Dead	Fence within falling distance     Fence under canopy     Shed - underneath tree and     greenhouse within falling distance	Branch stubs present     Crown lifted - over the site boundary historically     Crown shape distorted due to group pressure     Dead tree     Dutch Elm Disease     Iyy or climbing plants     Iyy covered tree     Wildlife habitat	- Fell Broadleaves - for reasons of health and safety within 3 months	Priority	Likely	Medium	Minor damage	Slight
SgI/001248	4	Acer platanoides (Norway Maple)	No	No	Eastern boundary	,	3	1	12	10	73	Middle aged	Normal	Fair	- Building within falling distance - greenhouse - Fence within falling distance - Fence under canopy - Wildlife Habitat	-Crown shape distorted due to group pressure - lay or climbing plants - lay covered tree - Low hanging branches - Minor dead wood <50mm - Multi stemmed - Trifurcated - Unable to fully assess due to ivy	- Lift canopy to 3m - over the allotment within months for reasons of health and safety - Sever climbing plant - within 12 months to aid with future inspections	Priority	None apparent	Low	Fragile objects	Insignificant

Client			Ando	over T	Town Council					Arborio	ultural C	onsultant			Amelia Williams MICFor, CEnv, MArbo	Weather	at time of	Cold, dry	Cold, dry, light breeze.			
Site location	on		Adm	irals \	Way Allotments, A	Andover				Site ob	servation	s				e outside edge to the Western bound Boundaries are fenced with ivy-clad p						
Date of the	e tree :	survey	22.11.	2023						Designa	ntions				No Tree Preservation Order (TPO) confirmed by TVBC on 06.11.2023 and site not within a Conservation Area (CA)			Plotted	Yes on Ezytre tagged	ev but not	Next inspection date	2028
Full Code	Seq No	Species (Botanical name / Common name)	Ash	Privat	te Tree Position	Addn. Position	No. of Stems	No. of Trees	Height (m)	Spread (m (d))	Trunk diameter (cm)	Age range	Vigour	Condition	n Site features	Tree considerations	Tree management recommendations	Priority for tree work	Failure (THREATS)	Target (THREATS)	Impact (THREATS)	Risk Cat (THREATS)
Wdl/ 001249	WI	Mixed broadleaves Acer platanoides - (256) Crataegus monogna - (256) Euonymus europaeus - (26) Fraxinus excelsior - (1788) Prunus avium - (51) Salik caprea - (26) Ulmus glabra - (153)		Yes	Offsite woodland	Eastern boundary	2556	2556	13	5	30	Young	Normal	Fair	- Fence within falling distance - Fence under canopy - Wildlife Habitat - Woodland edge tree - Within woodland	- Ash dieback - Ash stage 1 = 76-100% canopy remaining - Ash stage 2 = 51-75% canopy remaining - Crown shape distorted due to group pressure - Dutch Elm Disease - Epicormic growth - Historical branch loss - Ivy or climbing plants - Ivy covered tree - Low hanging branches - Major dead wood > 50mm - Multiple dead branches - Minor dead wood > 50mm - Multiple dead branches - Minor dead wood > 50mm - Multi stemmed - Suppressed - Tall and etiolated due to group pressure - Unable to fully assess due to restricted access - Unable to fully assess due to restricted access	- Fell Broadleaves - Request HCC fell dead Elms adjacent the boundary to the allotment within 6 months for reasons of health and safety (x 3 tree) - Hedge pruning maintenance - Prune back overhang and branches growing through the fence for reasons of annual boundary maintenance of Ash, Norway Maple, Cherry and Hawthorn and Elder plus ivy, (x 8 tree) - Monitor (Annually) - HCC for Ash dieback (x 30 tree)	Routine	Potentially	Low	Minor damage	Insignificant
Sgl/001250	5	Prunus avium (Wild Cherry)	No	No	Eastern boundary		2	1	14	10	38	Mature	Normal	Fair	Building within falling distance - greenhouse and shed     Fence within falling distance     Fence under canopy     Wildlife Habitat	Bifurated     Crown shape distorted due to group pressure     by or climbing plants     by covered tree     Low hanging branches     Minor dead wood <50mm     Narrow or tight forks	- Lift canopy to 3m - over the allotment within months for reasons of health and safety - Sever climbing plant - within 12 months to aid with future inspections (x2)	Priority	None apparent	Low	Fragile objects	Insignificant
SgI/001251	6	Prunus avium (Wild Cherry)	No	No	Eastern boundary		3	1	5	4	17	Young	Normal	Fair	· Fence within falling distance	- Bifurcated - with one stem dividing again into two - Crown shape distorted due to group pressure lyo re climbing plants - Low hanging branches - Minor dead wood <50mm - Narrow or tight forks	- Lift canopy to 3m - over the allotment within months for reasons of health and safety	Priority	None apparent	Low	Fragile objects	Insignificant
SgI/001252	7	Ulmus glabra (Wych Elm)	No	Yes	Offsite private tree HCC	Eastern boundary	1	1	9	3	30	Young	Low	Dead	- Fence within falling distance - Fence under canopy	Branch stubs present Crown shape distorted due to group pressure Dead tree Dutch Elm Disease - top of one of the stems has already failed loy or climbing plants loy covered tree Unable to fully assess due to restricted access Wildlife habitat	Fell Broadleaves - Request HCC fell for reasons of health and safety on boundary	Priority	Likely	Medium	Minor damage	Slight
SgI/001253	8	Acer platanoides (Norway Maple)	, No	No	Eastern boundary		1	1	12	8	62	Middle aged	Low	Fair	- Building within falling distance - greenhouse - Fence within falling distance - Fence under canopy - Wildlife Habitat	Crown shape distorted due to group pressure I y or climbing plants I y covered tree Low hanging branches Major dead wood >50mm Minor dead wood <50mm Trifurcated Unable to fully assess due to ky	Remove dead wood (>50mm) - for reasons of health and safety within 3 months - Sever climbing plant - within 12 months to aid with future inspections	Priority	Potentially	Low	Fragile objects	Insignificant
SgI/001254	9	Acer platanoides (Norway Maple)	No	No	Eastern boundary		1	1	11	11	52	Middle aged	Normal	Good	Building within falling distance - greenhouse and shed -Fence within falling distance -Fence under canopy -Shed -Wildlife Habitat	- Crown shape distorted due to group pressure - dominant side branch to North - Ivy or climbing plants - Ivy cowered tree - Low hanging branches - Minor dead wood *50mm - Unable to fully assess due to ivy	Lift canopy to 3m - over shed roof within 3 months     Sever climbing plant - within 12 months to aid with future inspections	Priority	Potentially	Low	Minor damage	Insignificant
SgI/001255	10	Acer platanoides (Norway Maple)	No No	Yes	Private offsite Eastern boundary	HCC owned	1	1	9	4	20	Young	Normal	Fair	- Fence within falling distance - Fence under canopy - Shed	Branch stubs present     Crown shape distorted due to group pressure     Ny or climbing plants     Low hanging branches     Suppressed     Unable to fully assess due to restricted access	- Lift canopy to 3m - over shed roof within 3 months	Priority	None apparent	Low	Fragile objects	Insignificant

Client	Client Andover Town Council			Arboric	ultural Co	nsultant			Amelia Williams MICFor, CErn, Marbora, BSc (Hons), Cert Ed.F.E., Dip Arb L6 (ABC), Cert Arb L4 (ABC)				at time of	ne of Cold, dry, light breeze.								
Site location	Site location Admirals Way Allotments, Andover				Site obs	ervations	•				ne padlocked gate. Overhead services along the wned land managed by Aster Property Services.											
Date of the	Date of the tree survey 22.11.2023				Designa	tions				No Tree Preservation Order (TPO) confirmed by TVBC on 06.11.2023 and site not within a Conservation Area (CA)			Plotted	Yes on Ezytree tagged		Next inspection date	2028					
Full Code	Seq No	Species (Botanical name / Common name)	Ash	Private	e Tree Position	Addn. Position				Spread (m (d))		Age range	Vigour	Condition	Site features	Tree considerations	Tree management recommendations	Priority for tree work	Failure (THREATS)	Target (THREATS)	Impact (THREATS)	Risk Cat (THREATS)
SgI/001256	11	Acer platanoides (Norway Maple)	No	Yes	Private offsite Eastern boundary	HCC owned	1	1	9	4	21	Young	Normal	Fair	- Fence within falling distance - Fence under canopy	Branch stubs present - where historically crown lifted win shape distorted due to group pressure - Epicormic growth - growing through fence - ly or climbing plants - Suppressed - Unable to fully assess due to restricted access	- Sever climbing plant - Recommended HCC sever the ivy to aid future inspections	Routine	None apparent	Low	Fragile objects	Insignificant
SgI/001257	12	Fraxinus excelsior (Common Ash)	Yes	No	Eastern boundary		1	1	13	11	65	Middle aged	Normal	Good	- Building within falling distance - greenhouses v2 and sheds - Fence within falling distance - Fence under canopy - Wildlife Habitat	Ash dieback     Ash stage 1 = 76-100% canopy remaining     Crown shape distorted due to group pressure     Fungal fruiting bodies - on old pruning wound     on trunk at 2 m above ground level     Ivy or climbing plants     Ivy covered tree     Minor dead wood <50mm     Multiple old pruning wounds     Occluded pruning wounds     Occluded pruning wounds     Occluding pruning wounds     Unable to fully assess due to ivy	Monitor (Annually) - Ash dieback     Sever climbing plant - within 12     months to aid with future inspections	Routine	Potentially	Low	Minor damage	Insignificant
SgI/001258	13	Fraxinus excelsior (Common Ash)	Yes	No	Eastern boundary		1	1	13	5	50	Middle aged	Normal	Fair	- Building within falling distance - greenhouses x2 and sheds - Fence within falling distance - Fence under canopy - Wildlife Habitat	Ash dieback Ash stage 2 = 11.75% canopy remaining Crown shape distorted due to group pressure - Sapling Norway maple growing up adjacent ly or climbing plants ly covered the Minor dead wood <50mm Suppressed Unable to fully assess due to ivy	Monitor (Annually) - Ash dieback     Sever climbing plant - within 12     months to aid with future inspections	Routine	Potentially	Low	Minor damage	Insignificant
SgI/001259	14	Fraxinus excelsior (Common Ash)	Yes	No	Eastern boundary		1	1	15	15	69	Middle aged	Normal	Good	- Building within falling distance - sheds - Fence within falling distance - Fence under canopy - Wildlife Habitat	- Ash dieback - Ash stage 1 = 76-100% canopy remaining - Branch stubs present - Crown shape distorted due to group pressure - Epicormic growth - Ivy or climbing plants - Ivy covered tree - Major dead wood - 50mm - Minor dead wood - 50mm - Unable to fully assess due to ivy	- Remove dead wood (>50mm) - within onths for reasons of health and safety - Monitor (Annually) - Ash dieback - Sever climbing plant - within 12 months to aid with future inspections	Priority	Potentially	Low	Minor damage	Insignificant
Sgl/001260	15	Fraxinus excelsior (Common Ash)	Yes	Yes	Private offsite tree Eastern boundary	HCC owned	1	1	10	7	30	Young	Normal	Fair	- Fence within falling distance - Fence under canopy - Wildlife Habitat	- Ash dieback - Ash stage 1 = 76-100% canopy remaining - lay or climbing plants - lay covered tree - Minor dead wood s0mm - Unable to fully assess due to restricted access - Unable to fully assess due to by	- Monitor (Annually) - HCC for Ash dieback - Sever climbing plant - within 12 months to aid with future inspections	Routine	Potentially	Low	Minor damage	Insignificant
SgI/001261	16	Fraxinus excelsior (Common Ash)	Yes	No	Eastern boundary		6	1	12	9	46	Middle aged	Normal	Fair	- Fence within falling distance - Fence under canopy - Shed - within falling distance - Wildlife Habitat	-Ash dieback     -Ash stage 1 = 76-100% canopy remaining     -Ivy or climbing plants     -Ivy covered tree     -Minor dead wood <50mm     -Multi stemmed     -Unable to fully assess due to ivy	Monitor (Annually) - Ash dieback     Sever climbing plant - within 12     months to aid with future inspections	Routine	Potentially	Low	Minor damage	Insignificant
SgI/001262	17	Sambucus nigra (Common Elder)	No	No	Eastern boundary		8	1	4	6	15	Over mature	Low	Very poor	Fence within falling distance     Fence under canopy     Grass surround	- Dead / dying - Decay present - Fungal fruiting bodies - Multi stemmed - Wildlife habitat	- Pollard - at 1.5m but retain stems for wildlife within 3 months	Priority	Potentially	Low	Fragile objects	Insignificant
SgI/001263	18	Fraxinus excelsior (Common Ash)	Yes	No	Sothern boundary		1	1	12	6	30	Young	Normal	Fair	Fence within falling distance     Fence under canopy     Shed - within falling distance     Wildlife Habitat	- Ash dieback - Ash stage 1 = 76-100% canopy remaining - Ivy or climbing plants - Ivy covered tree - Minor dead wood <50mm - Unable to fully assess due to ivy	Monitor (Annually) - Ash dieback     Sever climbing plant - within 12     months to aid with future inspections	Routine	Potentially	Low	Minor damage	Insignificant

Client			And	over '	Town Council					Arborio	ultural C	onsultant			Amelia Williams MICFor, CEnv, MAri	borA, BSc (Hons), Cert Ed.F.E, Dip Arb L6 (ABC), Cert Arb L4 (ABC)		Weather survey	at time of	Cold, dry	, light breez	Đ.	
Site locatio	ite location			irals	Way Allotments, A	Andover				Site ob	servation	is			Access off Admirals Way from one padlocked gate. Overhead services along the outside edge to the Western boundary. Hamps! Western boundary and TVBC owned land managed by Aster Property Services. Boundaries are fenced with ivy-clad posts and ivy provide wildlife habitat.								
Date of the	tree :	survey	22.11.2023								ations				No Tree Preservation Order (TPO) confirmed by TVBC on 06:11.2023 and site not within a Conservation Area (CA)				Yes on Ezytre tagged	ytreev but not Next inspection date		2028	
Full Code	Seq No	o Species (Botanical name / Common name)	Ash	Priva	ite Tree Position	Addn. Position		No. of Trees		Spread (m (d))	Trunk diameter (cm)	Age range	Vigour	Condition	Site features	Tree considerations	Tree management recommendations	Priority for tree work	Failure (THREATS)	Target (THREATS)	Impact (THREATS)	Risk Cat (THREATS)	
Sgl/001264	19	Fraxinus excelsior (Common Ash)	Yes	No	Southern boundary		1	1	8	4	15	Young	Normal	Fair	- Fence within falling distance - Fence under canopy - Shed - within falling distance - Wildlife Habitat	- Ash dieback - Ash stage I = 76-100% canopy remaining - Ny or climbing plants - Ny covered tree - Minor dead wood <50mm - Unable to fully assess due to hy - unsuitable location up against fence to develop into a larger tree	Monitor (Annually) - Ash dieback     Sever climbing plant - within 12     months to aid with future inspections	Routine	Potentially	Low	Fragile objects	Insignificar	
SgI/001265	20	Fraxinus excelsior (Common Ash)	Yes	No	Southern boundary		1	1	9	4	15	Young	Normal	Fair	Fence within falling distance     Fence under canopy     Shed - within falling distance     Wildlife Habitat	- Ash dieback - Ash stage I = 76-100% canopy remaining - Ny or climbing plants - Ny covered tree - Minor dead wood <50mm - Unable to fully assess due to Ny - unsuitable location up against fence to develop into a larger	Monitor (Annually) - Ash dieback     Sever climbing plant - within 12     months to aid with future inspections	Routine	Potentially	Low	Fragile objects	Insignificar	
SgI/001266	21	Fraxinus excelsior (Common Ash)	Yes	No	Southern boundary		2	1	9	4	15	Young	Normal	Fair	- Fence within falling distance - Fence under canopy - Wildlife Habitat	- Ash dieback - Ash stage I = 76-100% canopy remaining - Crossing branches - Ivy or climbing plants - Unable to fully assess due to ky - unsuitable location up against fence to develop into a larger tree	- Fell Broadleaves - unsuitable location up against fence to develop into a larger tree, fell within 12 months	Routine	Potentially	Low	Fragile objects	Insignificar	
Sgl/001267	22	Sambucus nigra (Common Elder)	No	No	Eastern boundary		8	1	5	7	65	Over mature	Low	Poor	Fence within falling distance     Fence under canopy     Grass surround     Overhead services	Cavities present     Decay present     Fungal fruiting bodies     Hollowing     Multi stemmed     Wildlife habitat - bird boxes	Retain, no works currently recommended - for wildlife benefit	Routine	Potentially	Low	Fragile objects	Insignificar	
Grp/001268	G5	Mixed broadleaves Acer platanoides - (I) Cornus sanguinea - (6) Sambucus nigra - (2)	No	Ye	s Private offsite	Southern boundary	9	9	0	0	0		Normal	Fair	- Fence within falling distance - Fence under canopy - Overhead services - Shed	Crown shape distorted due to group pressure - majority of fisite some up against the fence and part within the site. Land owner outside the fence line is first. Valley Borough Council and above ground services are installed on this location.  - Wy or climbing plants - Low hanging branches - Multi stemmed	Hedge pruning maintenance - Prune back to the fence any overhang as par of the boundary fence maintenance annually. (x 7 tree)	Routine	None apparent	Low	Fragile objects	Insignificar	

# Tree survey general guidance notes

# Tree survey notes and guidance

The tree survey is a brief assessment of the trees at the time of the inspection from ground level for health and safety and to provide guidance on the short and long-term management of the tree stock within the site. It is not intended to be a guarantee of tree safety in any form, as trees are living changing dynamic organisms. Estimates for dimensions were used where access was restricted. General descriptive details were noted about trees including tree work recommendations. All the data gathered is recorded on a tablet using Ezytreev tree management software.

#### Full code

Each tree, group, hedge or woodland surveyed will be assigned a **reference number** which will relate to its location on a tree survey plan e.g. trees are a numerical number, groups have **G** at the start, shrubs have an **S**, and hedges have **H**.

# **Sequence number**

This is a user-defined sequence number applied to the tree survey order.

# **Species**

Tree species will be in both a common name and a botanical Latin name.

# **Group species**


Where groups or hedges are recorded with more than one species present, a count if possible will be carried out and associated with each tree and shrub species present.


# Tree position and additional position

This is the reference location for where the tree is located within a site with additional information on the exact location. The locations of the trees are also plotted against the mapping system on Ezytreev.

# Height

The dimensions are taken using a clinometer or where this is not possible they will be estimated and are given in metres.







Scale	1: 500
Date	22/11/2023



# **Canopy Spread**

This is taken in **metres** as a diameter across the width of the whole canopy or calculated from the cardinal points based on pacing the distance on the ground.

#### **Trunk**

Trunk/stem diameters are measured in **cm** at 1.5 metres above ground level for single-stemmed trees, or immediately above the root flare for multi-stemmed trees, using a specialist tape for converting the girth to a diameter measurement. Where access to the stem is not feasible an estimate will be made.

### No. of stems

The number of stems for a tree is recorded and also this relates to the number of trees or stems in a group, hedge or woodland.

#### **Notes**

Are general features of the site or tree not recorded in a specific field.

# Age

An assessment of a tree's age classification is made in terms of its maturity within the site's landscape and recorded thus: **Sapling / Young / Middle Aged / Mature / Over Mature / Veteran.** 

# **Vigour**

Is an assessment of the annual growth of the tree and the categories are low, normal, and strong.

# Condition

An assessment of a tree's overall condition is to be made as Good, Fair, Poor, or Dead.

Good	Generally in healthy condition and no structural defects observed
Fair	Condition satisfactory with minor structural defects that could be remediated with pruning or tree shows adaptation

Poor	Tree in decline,	of poor structural	form or of low health
------	------------------	--------------------	-----------------------

**Dead** Not alive

#### Live crown

Based on a percentage of remaining live crown 100-75% is healthy, 75-50%, 50-25%, 25-0%.

#### **Status**

Relates to the historical age-based assessment of trees and the criteria are Ancient, Veteran, Notable, Heritage or Champion.

#### Site features

These are a description of the location of where the tree, group or hedge is situated.

### **Tree conditions**

Tree attributes and observations are key descriptions of the tree, group or woodland including defects, problems and previous tree works.

### **Recommendations**

Preliminary tree management recommendations are recommended based on the assessment of the tree and will have a **time** scale for when the works should be carried out or within a time period.

# **Statutory designations**

Prior to proceeding with any of the recommendations made within the tree survey, it is essential to carry out a check to see if any statutory designations apply. If the trees are within a Conservation Area or the subject of a Tree Preservation Order, the permission of the Local Authority will be required prior to carrying out any tree works. Furthermore, if the works exceed 5 cubic metres in timber volume within one calendar quarter this may require a felling licence. In addition, it is important to note key ecological and wildlife considerations for example the potential for trees to be bat roots, or the nesting bird season and wildlife habit and only carry out works in the appropriate season unless the works are urgent.

# **Priority**

Timescale for carrying out any recommended works.

# Works due date

Date recommended works are due to be carried out by or within.

#### **Risk assessment**

The basis of the risk assessment is THREATS - Tree Hazard Risk Evaluation and Treatment System developed by Julian Forbes-Laird.

#### **Failure score**

Consideration of identified defects in relation to species/clone history, established failure criteria & time of year based on likelihood of failure rating of None apparent (0)/Potentially with time (0.8) / Likely, foreseeable (2) / Probable, Soon (8) / Imminent, Immediate (50).

# **Target score**

Consideration of impact radius identified defect against potential targets. Consideration of forward visibility available to drivers (Poor Forward Visibility / Good Forward Visibility) and whether vehicles are likely to be stationary e.g. at junctions. If targets liable to include unsupervised children &/or the elderly or infirm, upgrade the target category by one category. For railway targets use THREATS NR. Target score based on **None (0) / Very low (7) / Low (15) / Medium (20) / High (25) / Very High (40).** 

# **Impact score**

Consideration of height of fall/momentum & whether e.g. lower branches would impeded agent's descent based on degree of harm and consequence. Scores are outlined below.

- 1 = Fragile objects destroyed, superficial or recoverable injury to pedestrians
- 4 = Minor damage, probable disabling, hospitalising injury to pedestrians
- **6**= Moderate structural severe vehicle damage, fatal disabling injuries likely
- **10** = Severe structural damage, vehicle crushed, passenger fatalities very probable.

# **Risk evaluation**

This is the total score from the **Failure score X Target score X Impact score** which then is put against one of the following score ranges 0-49 / 50-159 / 160-329 / 330 - 999 / 1000-2000 / 2001 - 3999 / 4000+

# Risk / Threat category

This is based on where the score sits within the score ranges

0-49 = **1 - Insignificant** (Re-inspect within 5 years if general public access or 3 years if child specific access & TS>20)

50-159 = **2-Minimal** (Reinspect within 3 years if public access, schedule work as required)

160-329 = **3 - Slight** (Reinspect annually / after storms (Force 10+), expect to schedule work within 2 years)

330 - 999 = **4-Moderate** (Reinspect within 13 weeks, reinspect after SWE meantime (inc glad to Force 7+)

1000-2000 = **5 - Significant** (Arrange for work to be completed within four weeks maximum) 2001 - 3999 = **6-Serious** (Close site if practical; arrange for work to be completed within 7 days) 4000+ = **7 - Extreme** (Evacuate/prevent access to site, emergency call out of contractors).

#### **Timescale**

**Inspection frequency is** based on the outcome of risk and recommendations ie within a set time period of months, annually, 3 years and up to 5 years.

# **Works already completed**

Where works recommended have been completed whilst on site.

# **Next inspection date**

The date for the next inspection is scheduled per tree based on the assessment of requirements and risk factors.

# **Photographs**

A photo where possible will be taken of each tree at the time of the tree survey or site visit including any additional photographs of specific defects.

# Ivy as a tree survey limitation on site

Where ivy is present it is not possible at the time of the survey to fully assess the condition of the stem or stems and when ivy covers the tree the same applies. A follow-up re-inspection would be recommended following the severance or removal of ivy to enable a further assessment.

# **Contact details**

**Amelia Williams** MICFor, CEnv, MArborA, BSc (Hons), Cert Ed.F.E, Dip Arb L6 (ABC), Cert Arb L4 (ABC) Arboricultural Consultant & Director

07740 868256 amelia@arb.company The Arboricultural Company Ltd www.arb.company