



#### Health and Safety Tree Survey for Churchill Way Allotment site, Andover (November 2023)

Client			ver Town Council			Arboric	ultural Co	nsultant			Amelia Williams MICFor, CEnv, MArborA, BSc (Hons), Cert Ed.F.E, Dip Arb L6 (ABC), Cert Arb L4 (ABC)			Weather at time of survey Cold, dry, light breeze.						
Site location			Churchill Way Allotments, Andover										Access off Admirals Way from one padloc	ked gate. Overhead services along the outside	edge to the Western boundary. Hampshire Co	unty Council ov	nty Council owned woodland to the Western bound			
Date of the tree survey		22.11.2023											owned land managed also the North, West and South. Boundaries are fenced with ivy-clad posts and ivy and bramble around fence li  No Tree Preservation Order (TPO) confirmed by TVBC on 06.11.2023 and site not within a Conservation Area (CA)			es and these pr	Provide wildlife habitat.  Yes on Ezytreev but not Next			2028
																	tagged		inspection	
Full Code Seq	No Species (Botanical name / Common name)	Ash	Private Tree Position	Addn. Position	No. of	No. of Trees	Height	Spread	Trunk	Age range	Vigour	Condition	Site features	Tree considerations	Tree management recommendations	Priority for tree	Failure	Target	Impact	Risk Cat (THREATS)
					Stems		(m)	(m (d))	diameter (cm)							work	(THREATS)	(THREATS)	(THREATS)	
Hdg/001269 H	11 Hedge - Mixed Species Acer platanoides - (28) Cornus sanguinea - (2) Crataegus monogyna - (3) Fraxinus excelsior - (1) Hedera helix - (51) Syringa vulgaris - (3)	Yes	No Around entire boundary	on and off site	88	88	3	3	15	Young	Normal	Fair	- Fence within falling distance - Fence under canopy - Gate or entrance - Parking within falling distance - Road within falling distance - Street lamp - x4	Crown shape distorted due to group pressure- partially on both sides of fence     Hy or climbing plants     Hy overed the Hy overed the     Low hanging branches     Multi stemmed	- Fell saplings - Norway maple predominantly around boundary as part of annual boundary maintenance (x 29 tree) - - Prune back overhang from garden - Prune back overhanging branches from off site that overhanging to the site within 17 months (x 5 tree) sever climbing plant - Sever and remove by from fence and fence posts annually as part of fence maintenance (x 51 tree)		None apparent	Medium	Fragile objects	Insignificant
Sgl/001270 1	Acer platanoides (Norway Maple)	No	No Northern boundary	by pedestrian gate entrance	3	1	4	3	20	Young	Normal	Fair	Fence within falling distance     Fence under canopy     Gate or entrance     Parked cars     Parking within falling distance	Bifurcated     Developing young tree - inappropriate location to grow on up against the fence     Poor shape and form	- Fell Broadleaves - within 6 months as inappropriate location - Stump - Chemically treat stump (eco plug)	Routine	None apparent	Medium	Fragile objects	Insignificant
Sgl/001271 2	Fraxinus excelsior (Common Ash)	Yes	No Northern boundary	up against fence	1	1	4	2	15	Young	Normal	Fair	Fence within falling distance     Fence under canopy     Parked cars     Parked cars     Parking within falling distance	- Ash dieback - Ash stage 1 = 76-100% canopy remaining - Developing young tree - inappropriate location to grow on up against the fence, bug hotel on trunk - lyy or climbing plants - lyy covered tree - Poor shape and form	- Fell Broadleaves - within 6 months as inappropriate location and Ash dieback - Stump - Chemically treat stump (eco plug)	Routine	Potentially	Medium	Fragile objects	Insignificant
Sgl/001272 3	Fraxinus excelsior (Common Ash)	Yes	No Northern boundary	up against fence	1	1	7.5	2	10	Young	Normal	Fair	- Fence under canopy - Grass surround - Parked cars	- Ash dieback - Ash stage 1 = 76-100% canopy remaining - Developing young tree - Ivy or climbing plants - Ivy covered tree	Fell Broadleaves - within 6 months as inappropriate location and Ash dieback     Stump - Chemically treat stump (eco plug)	Routine	Potentially	Medium	Minor damage	Minimal
SgI/001273 4	Acer platanoides (Norway Maple)	No	No Northern boundary	up against fence	1	1	8.5	4	15	Young	Normal	Fair	- Fence under canopy - Grass surround - Parked cars	Developing young tree     Ivy or climbing plants     Ivy covered tree	Fell Broadleaves - within 6 months as inappropriate location     Stump - Chemically treat stump (eco plug)	Routine	None apparent	Medium	Minor damage	Insignificant
Sgl/001274 5	Acer platanoides (Norway Maple)	No	Yes Off site private tree Northern boundary	TVBC owned	1	1	9	5.5	30	Young	Normal	Fair	Building within falling distance     Fence under canopy     Parked cars	Developing young tree hy or climbing plants Upon climbing plants Upon the plants of the Bungalow Site which is leased from Test Valley Borough Council Unable to fully assess due to by	Sever climbing plant - to aid future inspections	Routine	None apparent	High	Minor damage	Insignificant
Sgl/001275 6	Acer platanoides (Norway Maple)	No	Yes Off site private tree Eastern boundary	TVBC owned	1	1	8	3	15	Young	Normal	Fair	- Building within falling distance - Fence under canopy	Developing young tree     Ivy or climbing plants     Unable to fully assess due to restricted access - Tree within the grounds of The Bungalow Site     which is leased from Test Valley Borough Council	None required at the time of the survey.	No action required	None apparent	High	Minor damage	Insignificant
Sgl/001276 7	Acer pseudoplatanus (Sycamore)	No	Yes Off site private tree Eastern boundary	TVBC owned	1	1	18	16	65	Mature	Normal	Fair	- Building within falling distance - Fence under canopy - Shed	- Bat potential - bat box on trunk - Branch stubs present - Epicormic group bath - No overed tree - severed but not fully died off, studies and tree - severed but not fully died off, studies and wood - Somm - Minor dead wood - Somm - Narrow forks with included bark - Unable to fully assess due to restricted access- Tree within the grounds of The Bungalow Site which is leased from Test Valley Borough Council - Unable to fully assess due to iny	-Remove dead wood (>50mm) - Request via TVBC within 3 months for health and safety reasons - Lift cancy to 3m - Request via TVBC within 3 months for health and safety reasons - Seever (imbing plant - Request via TVBC within months for health and safety reasons to ald with future inspections	Priority 3	None apparent	High	Minor damage	Insignificant
Sgl/001277 8	Malus domestica (Bramley apple)	No	Ves Off site private tree Eastern boundary	TVBC owned	1	1	6	6	35	Mature	Normal	Fair	Building within falling distance - shed under canopy     Fence under canopy	- Branch stubs present - lyy or dimbing plants - lyy covered tree - Low hanging branches - Low hanging branches - Low banging branches - Tree within the grounds of The Bungalow Site which is leased from Test Valley Borough Council - Unable to fully assess due to hy	Sever climbing plant - Request via TVBC within months for health and safety reasons to reduce crown weight overhanging boundary and shed	3 Priority	Potentially	Low	Minor damage	Insignificant
Grp/001278 <b>G</b>	Mixed broadleaves Acer platanoides - (2) Acer pseudoplatarus - (1) Cornus sanguinea - (4) Crataegus monogyna - (1) Fraxinus excelsior - (5) Prunus avimus excelsior - (2) Rhamnus cathartica - (2) Tilia x europaea - (7)	Yes	Yes Off site private trees Eastern boundary	TVBC and HCC	24	24	17	7	50	Middle aged	Normal	Good	- Ditch - Fence within falling distance - Fence under canopy - Shed	- Ash dieback - Ash stage 1 = 76-100% canopy remaining - Basal suckers - Branch stubs present - Coppice stool - lapsed - Crown shape distorted due to group pressure - Epicormic growth - Ny or climbing plant - Now Person	- Lift canopy to 3m - Predominantly the 7 Lime trees off-size within 3 months for health and safety (x. 7 tree - Monitor (Annualy) - HHC/TVBC for Ash diebaci off-size boundary trees (x. 5 tree) - Sever climbing plant - TVBC? HCC - Within 12 months to aid future inspections (x. 20 tree)	Priority	None apparent	Low	Minor damage	Insignificant
SgI/001279 9	Sambucus nigra (Common Elder)	No	No Within the site by access track		2	1	4	3	17	Middle aged	Low	Dead	- Shed - Track	Bifurcated     Dead tree     Ivy or climbing plants     Ivy covered tree	Fell Broadleaves - within 1 month for reasons of health and safety     Stump - Grind out stump	Priority	Likely	Low	Minor damage	Minimal

Client				Andover Town Council								sultant			Amelia Williams MICFor, CEnv, MArborA, BSc (Hons), Cert Ed.F.E, Dip Arb L6 (ABC), Cert Arb L4 (ABC)			Weather at time of survey		Cold, dry, light breeze.		c c
			Churc	Churchill Way Allotments, Andover							vations				Access off Admirals Way from one padlocked gate. Overhead services along the outside edge to the Western boundary. Hampshire County Coowned land managed also the North, West and South. Boundaries are fenced with ivy-clad posts and ivy and bramble around fence lines and							
			22.11.2023							Designations					No Tree Preservation Order (TPO) confirmed by TVBC on 06.11.2023 and site not within a Conservation Area (CA)			Plotted	Yes on Ezytreev but tagged		Next inspection date	2028
Full Code	Seq No	Species (Botanical name / Common name)	Ash	Private	Tree Position	Addn. Position	No. of Stems	No. of Trees	Height S (m) (r		Trunk diameter (cm)	Age range	Vigour	Condition	Site features	Tree considerations	Tree management recommendations	Priority for tree work	Failure (THREATS)	Target (THREATS)	Impact (THREATS)	Risk Cat (THREATS)
Sgl/001280	10	Fagus sylvatica (Common Beech)	No	Yes	Off site private tree	Southern boundary	1	1	12	7	30	Young	Normal	Fair	- Building within falling distance - Fence within falling distance - Fence under canopy - Garden	Crown lifted     Developing young tree     Multiple old pruning wounds     Occluded pruning wounds     Occluding pruning wounds     Occluding pruning wounds     Unable to fully assess due to restricted access	None required at the time of the survey.	No action required	None apparent	High	Fragile objects	Insignificant
Sgl/001281		Aesculus hippocastanum (Horse Chestnut)	No	Yes	Off site private tree	Western boundary TVBC owned	1	1	12	9	69	Middle aged	Normal	Fair	- Building within falling distance - shed - Fence within falling distance - Fence under canopy - Grass surround - Road within falling distance - Road within falling distance	Crown reduced Crown inted Historical branch loss - recent limb failure onto shed roof in September 2023 and subsequent crown reduction carried out - lyo crowned tree - lyo covered tree - Nutliple of the mine younds - Occluding pruning wounds - Occluding pruning wounds	None required at the time of the survey.	No action required	None apparent	Medium	Minor damage	Insignificant
SgI/001282	12	Corylus avellana (Hazel)	No	No	Western boundary		10	1	4	3	45	Middle aged	Normal	Good	- Fence within falling distance - Fence under canopy	Coppice stool     Low hanging branches     Multi stemmed	· Coppice - within 12 months and on a cyclical basis every 5 years	Routine	None apparent	Low	Fragile objects	Insignificant





# Tree survey general guidance notes

# Tree survey notes and guidance

The tree survey is a brief assessment of the trees at the time of the inspection from ground level for health and safety and to provide guidance on the short and long-term management of the tree stock within the site. It is not intended to be a guarantee of tree safety in any form, as trees are living changing dynamic organisms. Estimates for dimensions were used where access was restricted. General descriptive details were noted about trees including tree work recommendations. All the data gathered is recorded on a tablet using Ezytreev tree management software.

#### Full code

Each tree, group, hedge or woodland surveyed will be assigned a **reference number** which will relate to its location on a tree survey plan e.g. trees are a numerical number, groups have **G** at the start, shrubs have an **S**, and hedges have **H**.

# **Sequence number**

This is a user-defined sequence number applied to the tree survey order.

# **Species**

Tree species will be in both a common name and a botanical Latin name.

# **Group species**

Where groups or hedges are recorded with more than one species present, a count if possible will be carried out and associated with each tree and shrub species present.

# Tree position and additional position

This is the reference location for where the tree is located within a site with additional information on the exact location. The locations of the trees are also plotted against the mapping system on Ezytreev.

# Height

The dimensions are taken using a clinometer or where this is not possible they will be estimated and are given in metres.

# **Canopy Spread**

This is taken in **metres** as a diameter across the width of the whole canopy or calculated from the cardinal points based on pacing the distance on the ground.

#### **Trunk**

Trunk/stem diameters are measured in **cm** at 1.5 metres above ground level for single-stemmed trees, or immediately above the root flare for multi-stemmed trees, using a specialist tape for converting the girth to a diameter measurement. Where access to the stem is not feasible an estimate will be made.

### No. of stems

The number of stems for a tree is recorded and also this relates to the number of trees or stems in a group, hedge or woodland.

#### **Notes**

Are general features of the site or tree not recorded in a specific field.

# Age

An assessment of a tree's age classification is made in terms of its maturity within the site's landscape and recorded thus: **Sapling / Young / Middle Aged / Mature / Over Mature / Veteran.** 

# **Vigour**

Is an assessment of the annual growth of the tree and the categories are low, normal, and strong.

# Condition

An assessment of a tree's overall condition is to be made as Good, Fair, Poor, or Dead.

Good	Generally in healthy condition and no structural defects observed
Fair	Condition satisfactory with minor structural defects that could be remediated with pruning or tree shows adaptation

Poor	Tree in decline,	of poor structural	form or of low health
------	------------------	--------------------	-----------------------

**Dead** Not alive

#### Live crown

Based on a percentage of remaining live crown 100-75% is healthy, 75-50%, 50-25%, 25-0%.

#### **Status**

Relates to the historical age-based assessment of trees and the criteria are Ancient, Veteran, Notable, Heritage or Champion.

#### Site features

These are a description of the location of where the tree, group or hedge is situated.

### **Tree conditions**

Tree attributes and observations are key descriptions of the tree, group or woodland including defects, problems and previous tree works.

### **Recommendations**

Preliminary tree management recommendations are recommended based on the assessment of the tree and will have a **time** scale for when the works should be carried out or within a time period.

# **Statutory designations**

Prior to proceeding with any of the recommendations made within the tree survey, it is essential to carry out a check to see if any statutory designations apply. If the trees are within a Conservation Area or the subject of a Tree Preservation Order, the permission of the Local Authority will be required prior to carrying out any tree works. Furthermore, if the works exceed 5 cubic metres in timber volume within one calendar quarter this may require a felling licence. In addition, it is important to note key ecological and wildlife considerations for example the potential for trees to be bat roots, or the nesting bird season and wildlife habit and only carry out works in the appropriate season unless the works are urgent.

# **Priority**

Timescale for carrying out any recommended works.

# Works due date

Date recommended works are due to be carried out by or within.

#### **Risk assessment**

The basis of the risk assessment is THREATS - Tree Hazard Risk Evaluation and Treatment System developed by Julian Forbes-Laird.

#### **Failure score**

Consideration of identified defects in relation to species/clone history, established failure criteria & time of year based on likelihood of failure rating of None apparent (0)/Potentially with time (0.8) / Likely, foreseeable (2) / Probable, Soon (8) / Imminent, Immediate (50).

# **Target score**

Consideration of impact radius identified defect against potential targets. Consideration of forward visibility available to drivers (Poor Forward Visibility / Good Forward Visibility) and whether vehicles are likely to be stationary e.g. at junctions. If targets liable to include unsupervised children &/or the elderly or infirm, upgrade the target category by one category. For railway targets use THREATS NR. Target score based on **None (0) / Very low (7) / Low (15) / Medium (20) / High (25) / Very High (40).** 

# **Impact score**

Consideration of height of fall/momentum & whether e.g. lower branches would impeded agent's descent based on degree of harm and consequence. Scores are outlined below.

- 1 = Fragile objects destroyed, superficial or recoverable injury to pedestrians
- 4 = Minor damage, probable disabling, hospitalising injury to pedestrians
- **6**= Moderate structural severe vehicle damage, fatal disabling injuries likely
- **10** = Severe structural damage, vehicle crushed, passenger fatalities very probable.

# **Risk evaluation**

This is the total score from the **Failure score X Target score X Impact score** which then is put against one of the following score ranges 0-49 / 50-159 / 160-329 / 330 - 999 / 1000-2000 / 2001 - 3999 / 4000+

# Risk / Threat category

This is based on where the score sits within the score ranges

0-49 = **1 - Insignificant** (Re-inspect within 5 years if general public access or 3 years if child specific access & TS>20)

50-159 = **2-Minimal** (Reinspect within 3 years if public access, schedule work as required)

160-329 = **3 - Slight** (Reinspect annually / after storms (Force 10+), expect to schedule work within 2 years)

330 - 999 = **4-Moderate** (Reinspect within 13 weeks, reinspect after SWE meantime (inc glad to Force 7+)

1000-2000 = **5 - Significant** (Arrange for work to be completed within four weeks maximum) 2001 - 3999 = **6-Serious** (Close site if practical; arrange for work to be completed within 7 days) 4000+ = **7 - Extreme** (Evacuate/prevent access to site, emergency call out of contractors).

#### **Timescale**

**Inspection frequency is** based on the outcome of risk and recommendations ie within a set time period of months, annually, 3 years and up to 5 years.

# **Works already completed**

Where works recommended have been completed whilst on site.

# **Next inspection date**

The date for the next inspection is scheduled per tree based on the assessment of requirements and risk factors.

# **Photographs**

A photo where possible will be taken of each tree at the time of the tree survey or site visit including any additional photographs of specific defects.

# Ivy as a tree survey limitation on site

Where ivy is present it is not possible at the time of the survey to fully assess the condition of the stem or stems and when ivy covers the tree the same applies. A follow-up re-inspection would be recommended following the severance or removal of ivy to enable a further assessment.

# **Contact details**

**Amelia Williams** MICFor, CEnv, MArborA, BSc (Hons), Cert Ed.F.E, Dip Arb L6 (ABC), Cert Arb L4 (ABC) Arboricultural Consultant & Director

07740 868256 amelia@arb.company The Arboricultural Company Ltd www.arb.company